

## 2017 REPAIR PRICE LIST - TONE

DAQ Part ID	Description	Repair Price
ACU-01210-E-XX	DR30E	\$909
ACU-01210-R-XX	DR30R	\$1,011
ACU-01825-XX	DT30	\$686
ACU-01280-XXX	DST30	\$340
ACU-01302-XXX	DSR30	\$365
ACU-01766-XX	DT10	\$525
ACU-01806-XX	DT30-3	\$620
ACU-01818-XX	DR10	\$630
ACU-02626	DM20	\$665
ACU-04157-XX	DAT300	\$690
ACU-04158-XX	DAR300	\$675
N/A	DAT30	\$650
N/A	DAR30	\$525
ACU-06151	DO10	\$140
ACU-06152	DD30	\$145
ACU-06153	DO30	\$260
ACU-06154	DF10	\$270
ACB-03949-X	LIU-4	\$80
ACB-03949-X	LIU-2	\$55
AEE-06468-XXXX	DXP2	\$390
ALP-01867-X	DLP7	\$220
APS-01777	DP115	\$245
ACU-01211-XX	DR30-19R	\$875
N/A	DT37	\$619
N/A	DPAR30	\$675
N/A	Bench Test Only	\$200
N/A	Test for Complete System	\$1,700