

2019 REPAIR PRICE LIST - SECURITY

| DAQ Part ID | Description | Repair Price |
|---------------|---|-----------------------|
| ACB-04641-3 | Digital Poller Mux - 8 RS485 Channel Board | \$678 |
| ACB-04641-4 | Digital Poller Mux - 8 RS232 Channel Board | \$678 |
| ACB-04704-0 | Audio Poller Mux - 8 Channel Board | \$651 |
| ACB-04704-1 | Audio Poller Mux - 16 Channel Board | \$1,366 |
| ACB-05028-0 | LIU-8 Board | \$269 |
| ACB-07583-XXX | StarGate III Board | \$624 |
| ACB-07584-000 | IAC III Board | \$500 |
| ACB-07637-1 | RIOX Board | Warranty Repairs Only |
| ACB-08123 | PMC Master Comm Board | \$65 |
| ACB-09651 | 202 Modem Board | \$108 |
| ACB-09812 | Ethernet Adapter Board | Warranty Repairs Only |
| ACB-09842 | Stargate III Indicator Module | Warranty Repairs Only |
| ACB-09842-P | Stargate III Indicator Module | Warranty Repairs Only |
| ACB-09923 | LIU-16 Board | \$334 |
| ACB-09925 | LIU-PMC Termination Board | \$370 |
| ACB-09942 | DX-PMC-LIU Board | \$189 |
| ACU-08314 | StarPAD Unit | \$307 |
| APS-08140 | ICIDS-IV PMC Bin Power Supply Panel Assembly | \$323 |
| APS-10123 | ICIDS-V PMC Bin Redundant Power Supply Assembly | \$500 |
| ENS-PANL | EntroStar Panel | \$452 |
| N/A | Bench Test Only | \$215 |
| N/A | Test for Complete Assembly (i.e. RADC-III, Local Controller, etc.) | \$753 |