

2017 REPAIR PRICE LIST - SECURITY

DAQ Part ID	Description	Repair Price
ACB-04641-3	Digital Poller Mux - 8 RS485 Channel Board	\$630
ACB-04641-4	Digital Poller Mux - 8 RS232 Channel Board	\$630
ACB-04704-0	Audio Poller Mux - 8 Channel Board	\$605
ACB-04704-1	Audio Poller Mux - 16 Channel Board	\$1,270
ACB-05028-0	LIU-8 Board	\$250
ACB-07583-XXX	StarGate III Board	\$580
ACB-07584-000	IAC III Board	\$465
ACB-07637-1	RIOX Board	Warranty Repairs Only
ACB-08123	PMC Master Comm Board	\$60
ACB-09651	202 Modem Board	\$100
ACB-09812	Ethernet Adapter Board	Warranty Repairs Only
ACB-09842	Stargate III Indicator Module	Warranty Repairs Only
ACB-09842-P	Stargate III Indicator Module	Warranty Repairs Only
ACB-09923	LIU-16 Board	\$310
ACB-09925	LIU-PMC Termination Board	\$345
ACB-09942	DX-PMC-LIU Board	\$175
ACU-08314	StarPAD Unit	\$285
APS-08140	ICIDS-IV PMC Bin Power Supply Panel Assembly	\$300
APS-10123	ICIDS-V PMC Bin Redundant Power Supply Assembly	\$465
ENS-PANL	EntroStar Panel	\$420
N/A	Bench Test Only	\$200
N/A	Test for Complete Assembly (i.e. RADC-III, Local Controller, etc.)	\$700