

2023 REPAIR PRICE LIST - SECURITY

DAQ Part ID	Description	Repair Price
ACB-04641-3	Digital Poller Mux - 8 RS485 Channel Board	\$750
ACB-04641-4	Digital Poller Mux - 8 RS232 Channel Board	\$750
ACB-04704-0	Audio Poller Mux - 8 Channel Board	\$750
ACB-04704-1	Audio Poller Mux - 16 Channel Board	\$1,505
ACB-05028-0	LIU-8 Board	\$300
ACB-07583-XXX	StarGate III Board	\$700
ACB-07584-000	IAC III Board	\$575
ACB-07637-1	RIOX Board	Warranty Repairs Only
ACB-08123	PMC Master Comm Board	\$75
ACB-09651	202 Modem Board	\$120
ACB-09812	Ethernet Adapter Board	Warranty Repairs Only
ACB-09842	Stargate III Indicator Module	Warranty Repairs Only
ACB-09842-P	Stargate III Indicator Module	Warranty Repairs Only
ACB-09923	LIU-16 Board	\$375
ACB-09925	LIU-PMC Termination Board	\$410
ACB-09942	DX-PMC-LIU Board	\$210
ACU-08314	StarPAD Unit	\$350
APS-08140	ICIDS-IV PMC Bin Power Supply Panel Assembly	\$400
APS-10123	ICIDS-V PMC Bin Redundant Power Supply Assembly	\$600
ENS-PANL	EntroStar Panel	\$500
N/A	Bench Test Only	\$275
N/A	Test for Complete Assembly (i.e. RADC-III, Local Controller, etc.)	\$850